

1998 Prevost Country Coach XLV - Non Slide

VIN: 2PCM33498W1026345

Miles: 164,572

Engine: Detroit S60 500 HP

Transmission: Allison 6spd

Generator: 17.5Kw PowerTech

Interior Color: Custom

Exterior Color: Custom

Cabinetry Color: Neutral

Slide-outs: 0

Length: 45'

STANDARD OPTIONS

- In motion satellite system
- 3 Rooftop A/C heat pumps
- 50,000 BTU diesel heat
- Zip Dee Awning package
- Polished stainless steel side panels
- Polished stainless steel rub rails
- Spotlight
- Silhouette shades
- Fiberglass painted fenders
- Hot / colder water manifold systems
- Hadley air horns
- Mood and aisle lighting throughout

FRONT/SALON

- Complete interior wall covering: Ultra-suede / mirrors
- Bose Lifestyle backup camera
- Phillips GPS system
- LED lighting throughout cabin
- Leather euro recliner & ottoman
- Fabric sofa sleeper (Recovered) / storage
- Ten disc player and sound system

GALLEY:

- Angle booth dinette
- Solid surface corian counters
- Large sink w/ cover
- Dishwasher
- Two burner electric cooktop
- Microwave / convection oven
- Washer / Dryer
- Built-in coffee maker
- Large residential refrigerator / freezer

- Ice / water dispenser
- Lighted display cabinet

STATEROOM / BATHROOM:

- Full sized tub w/ shower
- Large full length clothes closet
- Vanity w/ sink
- Vanity w/ sink and toilet in water closet
- Built-in laundry hamper
- Full length linen closet
- Queen bed
- Vanity w/ mirror and ottoman seat
- Rear hanging wardrobe
- Safe and storage under bed

EXTRAS:

- Upgraded Flat screen TV's
- Two satellite reciever
- Upgraded Sony radio system
- Exterior wash station
- Exterior electric grill
- Exterior 37' Vizio HDTV / swivel base
- Exterior Bose sound system
- Full length roof sides w/ complete rear air dam updating coach
- LED hard wired bay docking lights (48 LED's per light)
- Completely insulated tool bay and insulated front bumper bay

REFIT:

Complete length SIDE RAILS and REAR AIR DAM update of Coach	(2010)
Complete Prevost Specification Roof Removal and Refurbishment (Freightliner / Houston Body Shop)	(2014)
Exterior Paint Maintained and refurbished by Freightliner Paint & Body Shop	
Driver and Passenger Captain Chairs (Ultra leather)	(2017)
Driver's side window completely replaced (double pane)	(2017)
Front suspension:	
Remove and replace Upper and lower control Arms	(2017)
Replace Front Air Bags	(2017)
Left and Right Drive axle seals replaced	(2017)
Rear Drive axle brake assemblies replaced	(2017)
Main Engine Radiator NEW Replaced (Prevost Spec's)	(2017)
Complete Radiator Clutch Assembly	(2017)
Complete refurbish of radiator structure / refinish	(2017)
Complete Water Bay rebuild:	
New insulated bay and floor rebuild	(2017)
Two new 11.5 Gallon Acuuma Water heaters	(2017)
Two new high-volume water pumps	(2017)
Generator Radiator removed and replaced (NEW)	(2017)
Generator Starter replaced (NEW)	(2017)
Head Lights (NEW)	(2017)
Bay Door docking lights hard wired LEDS (48 LEDS / Light)	(2017)
Emergency LED STOP Light	(2017)
Front Windshield replaced	(2017)
Replaced with high volume Auxiliary Air Compressor	(2017)
Insulated Air Compressor bay	(2017)
Insulated Tool Compartment Bay	(2017)
Zip Dee Awning LOCK replacements (both ends)	(2017)
Tires and House / Chassis Batteries in excellent condition	
 New rear camera	 June 2018
New tires	May 2018
Eight new shocks	May 2018
Air dryer	May 2018
Engine & generator serviced	May 2018
Front end alignment	May 2018
Air valves replaced	September 2018
New KVH RV1 satellite	September 2018
New over the air antenna	September 2018
New BluRay player in salon & bedroom	September 2018